



# RADON ANALYSIS REPORT

1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1360305  
DATE RECEIVED: 07/15/2023  
REPORT DATE: 07/19/2023

### TEST LOCATION

JOHN DOE  
12345 SAMPLE STREET  
TULSA, OK 74137

ASSURED HOME INSPECTORS  
9548 E 108TH ST S TULSA, OK 74133

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

## HERE ARE YOUR TEST RESULTS

<u>VIAL #</u>	<u>ROOM TESTED</u>	<u>DATE OPENED</u>	<u>DATE CAPPED</u>	<u>DATE ANALYZED</u>	<u>RADON LEVEL</u>
5121108	BASEMENT FLOOR DINING ROOM	Jul 11, 2023 5:10 PM	Jul 14, 2023 1:10 PM	Jul 16, 2023 9:45 PM	0.3 pCi/L
5123896	BASEMENT FLOOR DINING ROOM	Jul 11, 2023 5:10 PM	Jul 14, 2023 1:10 PM	Jul 16, 2023 9:56 PM	< 0.3 pCi/L **

**AVERAGE RADON LEVEL (average result of two tests) : 0.3 pCi/L**

**\*\* One or more analysis results fall under the Lower Limit of Detection of 0.3 pCi/L.**

### THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCi/L) OR HIGHER

Please read the EPA Citizen's Guide to Radon at [www.epa.gov/radon/pubs/citguide.html](http://www.epa.gov/radon/pubs/citguide.html). Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at <http://njradon.org/download/mitbas.pdf>. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. **If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office.**

### LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Jose Figueroa, RMS  
NRPP CERT # 109347 RT  
NRSB CERT # 18SS007

PRO-LAB NRSB # ARL0028  
PRO-LAB NEHA ID # 101461AL

James E. McDonnell IV